
SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service Washington, DC





U.S. Department of Transportation

Federal Aviation Administration

No. CE-02-36 July 9, 2002

We post SAIBs on the internet at "av-info.faa.gov"

This is information only. Recommendations are not mandatory.

Introduction

This Special Airworthiness Information Bulletin (SAIB) advises you, owners and operators of Dornier Do 27 Q-6 model airplanes, of issuance of Dornier Service Bulletin (SB) SB-1141-0000.

Background

The FAA conducted a review of specified Dornier Do 27 series airplanes service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. Options included: Mandated compliance by initiation of a FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of Dornier Do 27 Q-6 model airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

There are also Dornier Do 27 model airplanes that are not type certificated. As the design of the certificated and non-certificated models may be similar, it is possible that identical problems could occur in the non-type-certificated models of the Do 27 airplanes.

Recommendations

The service bulletin identified in this document is not considered appropriate for AD action at this time; however, the FAA strongly suggests that all owners/operators of the Dornier Do 27 series airplanes review their compliance with the service bulletin listed below.

Dornier Do 27 Airplane Series Service Bulletin Number	MODEL	DATE	TITLE
SB-1141-0000	Do 27, all series	June 12, 2002	Inspection of Fuel Lines and Control Cables

The Service Bulletin Can Be Obtained From

Fairchild Dornier GmbH, PO Box 1103, D-82230 Wessling, Germany; Phone: (011) 49 81 53-30 0; Fax: (011) 49 81 53-30 29 01; www.fairchilddornier.com

For Further Information Contact

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 901 Locust Street, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov